

Application Note: Slow IR Response

If you have a CPU/XA or an Ocelot with all red indicator lights (Active, COMMS and X10) and you experience slow infrared response after loading application version 2.85 into your unit, you will need to remove the jumper from P2.

Ocelots with Red and Green indicator lights will not experience this problem.

Remove the top from the CPUXA or Ocelot. P2 is located above the indicator lights next to the voltage regulator and the battery.

